

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:			
Company	Boyd Rhodes		
OGM	Pete Hess Environmental Scientist III		
Company	Dan Guy		

Inspection Report

Permit Number:	C0070022		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, February 24, 2005		
Start Date/Time:	2/24/2005 12:30:00 PM		
End Date/Time:	2/24/2005 2:00:00 PM		
Last Inspection:	Monday, January 24, 2005		

Inspector: Pete Hess, Environmental Scientist III

Weather: <u>Sunny, clear; cool, 40's F.</u> InspectionID Report Number: 540

Accepted by: whedberg 3/8/2005

Permitee: SAVAGE SERVICES
Operator: SAVAGE SERVICES

Site: SAVAGE COAL TERMINAL

Address: 6340 S 3000 E STE 600, SALT LAKE CITY UT 84121

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership	Types of Operations

160.00	Total Permitted	☐ Federal	✓ Underground
122.28	Total Disturbed	☐ State	☐ Surface
	Phase I	☐ County	✓ Loadout
	Phase II	☐ Fee	Processing
	Phase III	✓ Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee continues to meet the Special Permit Condition included in Attachment "A" of the current State permit by submitting quarterly water monitoring information in an electronic form to the Division EDI.

There are no compliance actions currently pending for the Savage Coal terminal permit area.

The only permitting action currently pending is the update of required ownership and control information, Task ID#2029. Follow up is pending.

Inspector's Signature Date Thursday, February 24, 2005

Pete Hess, Environmental Scientist III Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Thursday, February 24, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓			
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check	✓		✓	
20.	Air Quality Permit	✓			
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Thursday, February 24, 2005 Page 3 of 3

4.a Hydrologic Balance: Diversions

The County has received copious amounts of moisture since the last inspection. The site's soil conditions are still very soft, preventing effective ditch maintenance from occurring. Runoff is pooled in certain areas. All ditches and culverts which were inspected appeared to be capable of functioning as designed.

16.a Roads: Construction, Maintenance, Surfacing

All of the roads being utilized by heavy trucks are in a graded, well compacted condition.

18. Support Facilities, Utility Installations

To date, the permittee has not initiated the construction of the maintenance shop which has been permitted through the Division (Task ID #2059, final OGM approval 12/23/2004). It is the Division's understanding that the financing of the project is still being evaluated.

19. AVS Check

According to Mr. Guy, the only outstanding permit amendment is the Chapter 1, Ownership and Control amendment submitted August 30, 2004. The status of this review is being investigated.